

Despite Alert, Flawed Wiring Still Kills G.I.'s

Saturday, 03 May 2008 14:33 -



Because of flawed electrical work by contractors, the bulletin stated, soldiers at American bases in Iraq had received severe electrical shocks, and some had even been electrocuted.

Since that warning, at least two more American soldiers have been electrocuted in similar circumstances. In all, at least a dozen American military personnel have been electrocuted in Iraq, according to the Pentagon and Congressional investigators.

[More...](#)